# Repairing 1999-2004 Honda Odyssey Rear window actuator

Quit replacing the rear window actuators at ~$200 to $300 each time they fail.

Written By: Marvin



# INTRODUCTION

The actuator failure occurs due to faulty design. Apparently replacement actuators are no better than the originals as they continue to fail. I did this to my Odyssey several years ago after both rear window actuators failed within months of each other. I have not had a single failure since applying this fix.


## TOOLS:

- Flathead Screwdriver (1)
- Large Needle Nose Pliers (1)
- Soldering Station (1)
- Phillips #2 Screwdriver (1)

## PARTS:

- 1/2" heat shrink 3" long (1)
- 2' 18 gauge high temperature insulation stranded wire (1)
- Rosin core solder (1)
- Two pack of 194LL turn signal/marker lamps (1)

## Step 1 — Repairing 1999-2004 Honda Odyssey Rear window actuator



- Download attached PDF.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-06-24 01:53:02 PM.